


Make:	Mitsubishi	Model:	Mirage
Body Style:	Hatchback	Year:	2021
Rego No.:	NKG36	Rego Expiry:	06 Oct 2026
WoF Expiry:	29 Jan 2027	Odometer:	61,783 Kms
Good No.:	27918598	VIN:	MMAXTA03AMH001009
Next Service:	70000	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Wet

Under Carriage and Under Bonnet Inspection Comments

Radiator mount rust.

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Road Conditions During Test Drive	Wet				
Engine Timing Mechanism	Timing Chain				
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Kms
Inspected by:	Darren Beban				
Published by:	Brandon Willmore				
Inspection Date:	20 Jan 2026				

I have read and understood
this condition guide:

NAME

SIGNATURE