


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Mitsubishi | Model: | Colt |
| Body Style: | Hatchback | Year: | 2004 |
| Rego No.: | MHT620 | Rego Expiry: | 19 Oct 2026 |
| WoF Expiry: | 15 Oct 2026 | Odometer: | 62,420 Kms |
| Good No.: | 27919003 | VIN: | 7AT0CJ0XX19103503 |
| Next Service: | 68,205 Kms | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Large dent in left rear quarter panel

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

2WD

Interior Comments

Seats: Stains. Slight wear on front seats

Carpets: Slight wear on drivers side

Panels: Good

Dashboard: Good

General Comments

Road Conditions During Test Drive Dry

Engine Timing Mechanism Cambelt

Evidence of Cam Belt Replacement Yes No Kms

Inspected by: Hoani Saunders

Published by: Robert Chardon

Inspection Date: 19 Jan 2026

I have read and understood
this condition guide:

NAME _____

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,919,003 | Version: | 1 |
| Created: | 20 Jan 2026 | | |

| | OK | Requires Attention | N/A |
|---|-----|--------------------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 5.2 | mm | |
| Right front | 5.2 | mm | |
| Left rear | 6.3 | mm | |
| Right rear | 6.3 | mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

SIGNATURE _____