


Make:	Mazda	Model:	Axela
Body Style:	Hatchback	Year:	2005
Rego No.:	HSC369	Rego Expiry:	14 Feb 2026
WoF Expiry:	29 Apr 2026	Odometer:	108,783 Kms
Good No.:	27920928	VIN:	7AT0C13JX14213530
Next Service:	?	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Paintwork clear coat has worn off bonnet, roof & top of rear tailgate.

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Brake pedal is very soft & has a lot of travel, needs attention.

Interior Comments

Seats:	Average
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

Holes in fabric on base pad & back rest of driver's seat.

Heater temperature & fan speed controls are not working.

Engine oil is very dirty, needs an engine service.

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Jason Young	
Published by:	Nick Beaton	
Inspection Date:	20 Jan 2026	

I have read and understood
this condition guide:

NAME _____

Report ID:	27,920,928	Version:	1
Created:	21 Jan 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance		✓	
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	6.0	mm	
Right front	4.5	mm	
Left rear	6.0	mm	
Right rear	4.0	mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE _____