


Make:	Volkswagen	Model:	Golf
Body Style:	Hatchback	Year:	2010
Rego No.:	NUU793	Rego Expiry:	31 Dec 2025
WoF Expiry:	02 Dec 2026	Odometer:	149,264 Kms
Good No.:	27921576	VIN:	WVWZZZ1KZAW330784
Next Service:	155,000 Kms	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Passenger side mirror glass held on by tape
Headlights yellowing
Windscreen has stone chips

Under Carriage and Under Bonnet Inspection Comments

FWD

Seats:	Average - Driver seat has slight tears
Carpets:	Good
Panels:	Average - Drivers door has scratches
Dashboard:	Good

Interior roof lining sagging
Maps not for NZ roads
Floor mats don't match

Inspected by:	Logan Lane
Published by:	Jaykib Collins
Inspection Date:	17 Jan 2026

I have read and understood
this condition guide:

NAME _____

SIGNATURE