

Report ID:	27,921,632	Version:	1
Created:	20 Jan 2026		


Make:	Mazda	Model:	Axela
Body Style:	Sedan	Year:	2015
Rego No.:	QNJ829	Rego Expiry:	07 Mar 2026
WoF Expiry:	10 Apr 2026	Odometer:	79,518 Kms
Good No.:	27921632	VIN:	7AT0C13JX22102277
Next Service:	73,000 kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

L front park light not working, drive belt cracked, trans oil leak, R front shock leak, L front inner guard missing, both front and L rear tyre cracked, service overdue.

Conditions During Body Inspection:  Dry  Wet

### Under Carriage and Under Bonnet Inspection Comments

### Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Good

### General Comments

Car vibration, windscreen cracked replaced, driver body seal torn, steering wheel worn,

Road Conditions During Test Drive	Wet		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Marlon Espena		
Published by:	Marlon Espena		
Inspection Date:	20 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			4 mm
Right front			4 mm
Left rear			6 mm
Right rear			6 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_