


Make:	Mazda	Model:	Atenza
Body Style:	Wagon	Year:	2006
Rego No.:	JBU449	Rego Expiry:	21 Jul 2026
WoF Expiry:	26 Jul 2026	Odometer:	319,823 Kms
Good No.:	27922663	VIN:	7AT0C139X15504251
Next Service:	Unknown	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Front grille is cracked. Minor stone cracks on windshield (1 in C.V.A.). Roof and rear spoiler paint is fading.

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**
**Interior Comments**

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Centre pocket lid is broken.

**General Comments**

AC is not cold. Left front window is not operating from main switch. Rattling and noise from around transmission,possible engine mount ,transmission mount?

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Yuki Itohara
Published by:	Tiaan Pienaar
Inspection Date:	19 Jan 2026

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	27,922,663	Version:	1
Created:	20 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise		✓	
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		3.5 mm	
Right front		3.0 mm	
Left rear		3.5 mm	
Right rear		4.5 mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation		✓	
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL			✓
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE \_\_\_\_\_