


Make:	Isuzu	Model:	D-MAX
Body Style:	Utility	Year:	2017
Rego No.:	RNC767	Rego Expiry:	
WoF Expiry:	19 Aug 2025	Odometer:	143,371 Kms
Good No.:	27925563	VIN:	MPATFS85JHT009472
Next Service:	Over due	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Windscreen stone chip cracked
 Front wheel mouldings need refit
 RR wheel mud flap needs refit
 Tools missing

Conditions During Body Inspection	Wet
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

4wd
 Engine oil leak
 Transmission oil leak
 Turbo oil leak

Interior Comments

Seats:	Good
Carpets:	Average
Panels:	Door trims scratches
Dashboard:	centre console lid needs refit

General Comments

Roof rack keys missing
 FR tyre scalloped

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Vasanthakumar Mayilswamy
Published by:	Vasanthakumar Mayilswamy
Inspection Date:	20 Jan 2026

I have read and understood
 this condition guide:

NAME _____

Report ID:	27,925,563	Version:	1
Created:	20 Jan 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front		4 mm	
Right front		0 mm	
Left rear		5 mm	
Right rear		5 mm	
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

SIGNATURE _____