


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | LDV         | Model:           | G10               |
| Body Style:   | Van         | Year:            | 2021              |
| Rego No.:     | NHQ502      | Rego Expiry:     | 17 Feb 2026       |
| WoF Expiry:   | 13 Oct 2026 | Odometer:        | 91,276 Kms        |
| Good No.:     | 27929476    | VIN:             | LSKG4GL12LA129642 |
| Next Service: | 89400       | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key

S = Scratch R = Rust C = Crack \* = Decals W = Significant scuffs  
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Body Inspection Comments

Windscreen cracked

Conditions During Body Inspection

Wet

## Under Carriage and Under Bonnet Inspection Comments

## Interior Comments

|            |      |
|------------|------|
| Seats:     | Poor |
| Carpets:   | Poor |
| Panels:    | Poor |
| Dashboard: | Poor |

## General Comments

Service, tyre pressure lights on  
Drive line/ diff whine

|                                   |  |
|-----------------------------------|--|
| Road Conditions During Test Drive | Wet  |
| Engine Timing Mechanism           | Timing Chain   |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes <input type="checkbox"/> No Kms |
| Inspected by:                     | Greg Morgan  |
| Published by:                     | Francois Kleyn   |
| Inspection Date:                  | 21 Jan 2026  |

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 27,929,476  | Version: | 1 |
| Created:   | 21 Jan 2026 |          |   |

|   | OK | Requires Attention | N/A    |
|---|----|--------------------|--------|
| <b>Engine</b>                                       |    |                    |        |
| Oil level   |    | ✓                  |        |
| Smoke & fumes                                       | ✓  |                    |        |
| Engine performance                                  | ✓  |                    |        |
| Noise   | ✓  |                    |        |
| Coolant condition                                   | ✓  |                    |        |
| Cooling performance                                 | ✓  |                    |        |
| Radiator / Hoses (visual)                           | ✓  |                    |        |
| <b>Transmission</b>                                 |    |                    |        |
| Operation   | ✓  |                    |        |
| Noise   |    | ✓                  |        |
| Clutch  | ✓  |                    |        |
| CV joints   |    |                    | ✓      |
| Wheel bearings                                      | ✓  |                    |        |
| <b>Brakes</b>                                       |    |                    |        |
| Performance   | ✓  |                    |        |
| Hand brake  | ✓  |                    |        |
| <b>Tyres (lowest observed tread depth of tyres)</b> |    |                    |        |
| Left front  |    |                    | 4.0 mm |
| Right front   |    |                    | 7.0 mm |
| Left rear   |    |                    | 2.0 mm |
| Right rear  |    |                    | 2.0 mm |
| Spare   |    | Yes                |        |
| <b>Suspension</b>                                   |    |                    |        |
| Suspension performance                              | ✓  |                    |        |
| Steering performance                                | ✓  |                    |        |
| Shock absorbers                                     | ✓  |                    |        |
| <b>Air Conditioning / Heater</b>                    |    |                    |        |
| Operation   | ✓  |                    |        |
| <b>Electrical / Accessories</b>                     |    |                    |        |
| Head lights   | ✓  |                    |        |
| Tail lights   | ✓  |                    |        |
| Indicators  | ✓  |                    |        |
| Dashboard warning lights                            |    | ✓                  |        |
| Wipers (front & rear)                               | ✓  |                    |        |
| Window winder FL                                    | ✓  |                    |        |
| Window winder FR                                    | ✓  |                    |        |
| Window winder RL                                    |    |                    | ✓      |
| Window winder RR                                    |    |                    | ✓      |
| Rear view mirrors                                   | ✓  |                    |        |
| Radio (basic test only)                             | ✓  |                    |        |
| CD (basic test only)                                |    |                    | ✓      |
| Number of keys                                      | 1  |                    |        |
| Central locking                                     | ✓  |                    |        |
| Remote locking                                      |    | ✓                  |        |
| Sat. nav. (basic test only)                         |    |                    | ✓      |
| Reversing camera                                    | ✓  |                    |        |

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_