


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Holden | Model: | Trax |
| Body Style: | SUV | Year: | 2015 |
| Rego No.: | RNT655 | Rego Expiry: | 17 Jul 2026 |
| WoF Expiry: | 09 Jan 2027 | Odometer: | 94,001 Kms |
| Good No.: | 27929725 | VIN: | KL3BA7689FB175337 |
| Next Service: | 95930 | Service History: | Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Rear spoiler faded
Reverse Camera blurry

| | |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

| | |
|------------|------|
| Seats: | Good |
| Carpets: | Good |
| Panels: | Good |
| Dashboard: | Good |

General Comments

| | | | | | |
|-----------------------------------|--------------------------|-----|--------------------------|----|-----|
| Road Conditions During Test Drive | Dry | | | | |
| Engine Timing Mechanism | Timing Chain | | | | |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> | Yes | <input type="checkbox"/> | No | Kms |
| Inspected by: | Kris Milne | | | | |
| Published by: | Kris Milne | | | | |
| Inspection Date: | 30 Jan 2026 | | | | |

I have read and understood
this condition guide:

NAME

SIGNATURE