


Make:	Volkswagen	Model:	Polo
Body Style:	Hatchback	Year:	2011
Rego No.:	NGG166	Rego Expiry:	24 Jul 2026
WoF Expiry:	16 Dec 2026	Odometer:	91,345 Kms
Good No.:	27929955	VIN:	WVWZZZ6RZCU022699
Next Service:	93,000 km	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Rear tailgate screen has delamination.

**Conditions During Body Inspection**

Dry

**Under Carriage and Under Bonnet Inspection Comments**

Oil leak underside.  
 Surface rust underside.  
 Rear tyres tread cracking.  
 R/F wheel has play.

**Interior Comments**

Seats: Average  
 Carpets: Average  
 Panels: Average  
 Dashboard: Average

**General Comments**

Airbag warning light ON.  
 Fault codes.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Inspected by:	Imraan Bryant
Published by:	Erin White
Inspection Date:	28 Jan 2026

I have read and understood  
 this condition guide:

NAME \_\_\_\_\_

Report ID:	27,929,955	Version:	1
Created:	30 Jan 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	5.0	mm	
Right front	5.0	mm	
Left rear	5.0	mm	
Right rear	5.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

SIGNATURE \_\_\_\_\_