


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Nissan      | Model:           | Navara            |
| Body Style:   | Utility     | Year:            | 2006              |
| Rego No.:     | KQW249      | Rego Expiry:     | 06 May 2026       |
| WoF Expiry:   | 13 Feb 2027 | Odometer:        | 240,460 Kms       |
| Good No.:     | 27934225    | VIN:             | VSKCLND40A0118140 |
| Next Service: | No History. | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Conditions During Body Inspection    Dry

**Under Carriage and Under Bonnet Inspection Comments**

**Interior Comments**

Seats: ok besides drivers side bolster ripped.  
 Carpets: Average  
 Panels: Average  
 Dashboard: Good

**General Comments**

Vehicle drove well.  
 No heat or cold air, air conditioning unit not responding no air coming out of vents.  
 LH rear window doesn't go up from drivers master switch, works fine from door.

|                                   |  |
|-----------------------------------|--|
| Road Conditions During Test Drive | Dry  |
| Engine Timing Mechanism           | Timing Chain   |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| Inspected by:                     | Jayden Roxburgh  |
| Published by:                     | Jayden Roxburgh  |
| Inspection Date:                  | 30 Jan 2026  |

I have read and understood  
 this condition guide:

NAME \_\_\_\_\_

|            |             |          |   |
|------------|-------------|----------|---|
| Report ID: | 27,934,225  | Version: | 4 |
| Created:   | 30 Jan 2026 |          |   |

|   | OK     | Requires Attention | N/A |
|---|--------|--------------------|-----|
| <b>Engine</b>                                       |        |                    |     |
| Oil level   | ✓      |                    |     |
| Smoke & fumes                                       | ✓      |                    |     |
| Engine performance                                  | ✓      |                    |     |
| Noise   | ✓      |                    |     |
| Coolant condition                                   | ✓      |                    |     |
| Cooling performance                                 | ✓      |                    |     |
| Radiator / Hoses (visual)                           | ✓      |                    |     |
| <b>Transmission</b>                                 |        |                    |     |
| Operation   | ✓      |                    |     |
| Noise   | ✓      |                    |     |
| Clutch  |        |                    | ✓   |
| CV joints   | ✓      |                    |     |
| Wheel bearings                                      | ✓      |                    |     |
| <b>Brakes</b>                                       |        |                    |     |
| Performance   | ✓      |                    |     |
| Hand brake  | ✓      |                    |     |
| <b>Tyres (lowest observed tread depth of tyres)</b> |        |                    |     |
| Left front  | 5.5 mm |                    |     |
| Right front   | 5.5 mm |                    |     |
| Left rear   | 5 mm   |                    |     |
| Right rear  | 5 mm   |                    |     |
| Spare   | Yes    |                    |     |
| <b>Suspension</b>                                   |        |                    |     |
| Suspension performance                              | ✓      |                    |     |
| Steering performance                                | ✓      |                    |     |
| Shock absorbers                                     | ✓      |                    |     |
| <b>Air Conditioning / Heater</b>                    |        |                    |     |
| Operation   |        | ✓                  |     |
| <b>Electrical / Accessories</b>                     |        |                    |     |
| Head lights   | ✓      |                    |     |
| Tail lights   | ✓      |                    |     |
| Indicators  | ✓      |                    |     |
| Dashboard warning lights                            | ✓      |                    |     |
| Wipers (front & rear)                               | ✓      |                    |     |
| Window winder FL                                    | ✓      |                    |     |
| Window winder FR                                    | ✓      |                    |     |
| Window winder RL                                    | ✓      |                    |     |
| Window winder RR                                    | ✓      |                    |     |
| Rear view mirrors                                   | ✓      |                    |     |
| Radio (basic test only)                             | ✓      |                    |     |
| CD (basic test only)                                | ✓      |                    |     |
| Number of keys                                      | 1      |                    |     |
| Central locking                                     | ✓      |                    |     |
| Remote locking                                      | ✓      |                    |     |
| Sat. nav. (basic test only)                         |        |                    | ✓   |
| Reversing camera                                    |        |                    | ✓   |

SIGNATURE \_\_\_\_\_