


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Suzuki | Model: | Swift |
| Body Style: | Hatchback | Year: | 2005 |
| Rego No.: | GPL861 | Rego Expiry: | 01 Feb 2026 |
| WoF Expiry: | 06 Feb 2027 | Odometer: | 138,333 Kms |
| Good No.: | 27938445 | VIN: | 7AT0GK0CX12647336 |
| Next Service: | 143,358 | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

| | |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

Under Carriage and Under Bonnet Inspection Comments

Oil Leak

Interior Comments

| | |
|------------|---------|
| Seats: | Average |
| Carpets: | Average |
| Panels: | Average |
| Dashboard: | Average |

General Comments

Head Unit Faulty
 Engine Ticking Noise
 Trans Whine in 1st Gear
 Left Front Shock Absorber Bouncy

| | | |
|-----------------------------------|--|-----|
| Road Conditions During Test Drive | Dry | |
| Engine Timing Mechanism | Timing Chain | |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes <input type="checkbox"/> No | Kms |
| Inspected by: | Samuel Weir | |
| Published by: | James Scott | |
| Inspection Date: | 27 Jan 2026 | |

I have read and understood
 this condition guide:

NAME _____

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,938,445 | Version: | 1 |
| Created: | 27 Jan 2026 | | |

| | OK | Requires Attention | N/A |
|---|-----|--------------------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | | ✓ | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 6.0 | mm | |
| Right front | 6.0 | mm | |
| Left rear | 6.0 | mm | |
| Right rear | 6.0 | mm | |
| Spare | N/A | | |
| Suspension | | | |
| Suspension performance | | ✓ | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | | ✓ | |
| CD (basic test only) | | ✓ | |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | | ✓ | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

SIGNATURE _____