


Make:	Mazda	Model:	Axela
Body Style:	Hatchback	Year:	2004
Rego No.:	PDF571	Rego Expiry:	20 Oct 2026
WoF Expiry:	28 Jan 2027	Odometer:	213,012 Kms
Good No.:	27940865	VIN:	7A8C13J0709106434
Next Service:	222,000 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front bumper detaching on right side

Front left wing mirror rear cover cracked

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

2WD

Transmission oil weep and seepage

Interior Comments

Seats:	Stains on rear seats, slight wear on drivers seat
Carpets:	Wear on drivers side
Panels:	Good
Dashboard:	Crack in top centre of dashboard

General Comments

Blowing smoke

Road Conditions During Test Drive	Dry				
Engine Timing Mechanism	Timing Chain				
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Kms
Inspected by:	Hoani Saunders				
Published by:	Miroslav Granich				
Inspection Date:	26 Jan 2026				

I have read and understood
this condition guide:

NAME

Report ID:	27,940,865	Version:	1
Created:	27 Jan 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes		✓	
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front		6.3 mm	
Right front		6.2 mm	
Left rear		4.4 mm	
Right rear		4.6 mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

SIGNATURE