


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Mazda       | Model:           | Verisa            |
| Body Style:   | Hatchback   | Year:            | 2007              |
| Rego No.:     | LAW77       | Rego Expiry:     | 17 May 2026       |
| WoF Expiry:   | 30 Sep 2026 | Odometer:        | 178,654 Kms       |
| Good No.:     | 27941003    | VIN:             | 7AT0C103X17311185 |
| Next Service: | unknown.    | Service History: | No                |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

R/F hubcap missing.  
 Both bumpers fitting poorly.  
 Right mirror not retracting.

|                                   |     |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

**Under Carriage and Under Bonnet Inspection Comments**

**Interior Comments**

|            |      |
|------------|------|
| Seats:     | Good |
| Carpets:   | Good |
| Panels:    | Good |
| Dashboard: | Good |

**General Comments**

Screeching on startup.  
 Key damaged.  
 Ac mode dial not working.  
 Rear wiper needs replacing.

|                                   |  |     |
|-----------------------------------|--|-----|
| Road Conditions During Test Drive | Dry  |     |
| Engine Timing Mechanism           | Timing Chain   |     |
| Evidence of Cam Belt Replacement  | <input type="checkbox"/> Yes <input type="checkbox"/> No | Kms |
| Inspected by:                     | LukaAjitvan Woerden                                      |     |
| Published by:                     | LukaAjitvan Woerden                                      |     |
| Inspection Date:                  | 28 Jan 2026  |     |

I have read and understood  
 this condition guide:

NAME \_\_\_\_\_

|   | OK  | Requires Attention | N/A |
|---|-----|--------------------|-----|
| <b>Engine</b>                                       |     |                    |     |
| Oil level   | ✓   |                    |     |
| Smoke & fumes                                       | ✓   |                    |     |
| Engine performance                                  | ✓   |                    |     |
| Noise   | ✓   |                    |     |
| Coolant condition                                   | ✓   |                    |     |
| Cooling performance                                 | ✓   |                    |     |
| Radiator / Hoses (visual)                           | ✓   |                    |     |
| <b>Transmission</b>                                 |     |                    |     |
| Operation   | ✓   |                    |     |
| Noise   | ✓   |                    |     |
| Clutch  |     |                    | ✓   |
| CV joints   | ✓   |                    |     |
| Wheel bearings                                      | ✓   |                    |     |
| <b>Brakes</b>                                       |     |                    |     |
| Performance   | ✓   |                    |     |
| Hand brake  | ✓   |                    |     |
| <b>Tyres (lowest observed tread depth of tyres)</b> |     |                    |     |
| Left front  | 3.0 | mm                 |     |
| Right front   | 5.5 | mm                 |     |
| Left rear   | 3.0 | mm                 |     |
| Right rear  | 2.5 | mm                 |     |
| Spare   | Yes |                    |     |
| <b>Suspension</b>                                   |     |                    |     |
| Suspension performance                              | ✓   |                    |     |
| Steering performance                                | ✓   |                    |     |
| Shock absorbers                                     | ✓   |                    |     |
| <b>Air Conditioning / Heater</b>                    |     |                    |     |
| Operation   | ✓   |                    |     |
| <b>Electrical / Accessories</b>                     |     |                    |     |
| Head lights   | ✓   |                    |     |
| Tail lights   | ✓   |                    |     |
| Indicators  | ✓   |                    |     |
| Dashboard warning lights                            | ✓   |                    |     |
| Wipers (front & rear)                               |     |                    | ✓   |
| Window winder FL                                    | ✓   |                    |     |
| Window winder FR                                    | ✓   |                    |     |
| Window winder RL                                    | ✓   |                    |     |
| Window winder RR                                    | ✓   |                    |     |
| Rear view mirrors                                   | ✓   |                    |     |
| Radio (basic test only)                             | ✓   |                    |     |
| CD (basic test only)                                | ✓   |                    |     |
| Number of keys                                      | 1   |                    |     |
| Central locking                                     | ✓   |                    |     |
| Remote locking                                      |     |                    | ✓   |
| Sat. nav. (basic test only)                         |     |                    | ✓   |
| Reversing camera                                    |     |                    | ✓   |

SIGNATURE \_\_\_\_\_