


Make:	Mitsubishi	Model:	ASX
Body Style:	SUV	Year:	2018
Rego No.:	LLC327	Rego Expiry:	18 Jun 2026
WoF Expiry:	25 Dec 2026	Odometer:	133,577 Kms
Good No.:	27945180	VIN:	JMFXTGA2WJU006639
Next Service:	143,000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Road Conditions During Test Drive	Dry				
Engine Timing Mechanism	Timing Chain				
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Kms
Inspected by:	Darren Beban				
Published by:	Desian Robb				
Inspection Date:	31 Jan 2026				

I have read and understood
this condition guide:

NAME

SIGNATURE