


Make:	Honda	Model:	Odyssey
Body Style:	People Mover	Year:	2008
Rego No.:	EMZ466	Rego Expiry:	26 Jul 2026
WoF Expiry:	16 Apr 2026	Odometer:	258,671 Kms
Good No.:	27946511	VIN:	JHMRB18508C203960
Next Service:	233,000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Minor stone chips in windscreen

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Left CV boots leaking grease
 Rust on front lower radiator support
 Non coolant leak at radiator
 Left rear shock absorber misting

Interior Comments

Seats:	Poor
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Passenger visor not fully retracting
 Humming noise above 50km
 Slight judder when applying brakes

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Darren Beban
Published by:	Desian Robb
Inspection Date:	30 Jan 2026

I have read and understood
 this condition guide:

NAME _____

Report ID:	27,946,511	Version:	1
Created:	04 Feb 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	5.0	mm	
Right front	4.5	mm	
Left rear	6.5	mm	
Right rear	2.5	mm	
Spare	Yes		
Suspension			
Suspension performance		✓	
Steering performance	✓		
Shock absorbers		✓	
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE _____