

Report ID:	27,951,104	Version:	1
Created:	03 Feb 2026		


Make:	Nissan	Model:	Navara
Body Style:	Utility	Year:	2013
Rego No.:	GZB592	Rego Expiry:	16 Mar 2026
WoF Expiry:	06 May 2026	Odometer:	175,909 Kms
Good No.:	27951104	VIN:	VSKCVND40A0457875
Next Service:	185,531kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Antenna missing, both L rear door switch fault, L rear body seal torn, exterior door plastic handle cover missing, coolant tank reservoir leak, underbody rust, engine oil leak, front brake and rotor low,

Conditions During Body Inspection    Dry

**Under Carriage and Under Bonnet Inspection Comments**

**Interior Comments**

Seats:	Average
Carpets:	Poor
Panels:	Average
Dashboard:	Average

**General Comments**

Noise power steering when full turn, L front indicator not working, L front wheel play,

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Marlon Espena	
Published by:	Marlon Espena	
Inspection Date:	03 Feb 2026	

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition		✓	
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance		✓	
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			5 mm
Right front			5 mm
Left rear			5 mm
Right rear			5.5 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance		✓	
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights		✓	
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_