


Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2022
Rego No.:	PBW909	Rego Expiry:	10 Mar 2026
WoF Expiry:	02 Sep 2026	Odometer:	60,300 Kms
Good No.:	27951877	VIN:	MMAJLKL10NH008318
Next Service:	71431	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Stone chip in CVA

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Average
Dashboard:	Good

General Comments

Road Conditions During Test Drive	Wet				
Engine Timing Mechanism	Timing Chain				
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input type="checkbox"/>	No	Kms
Inspected by:	Kris Milne				
Published by:	Kris Milne				
Inspection Date:	02 Feb 2026				

I have read and understood
this condition guide:

NAME

SIGNATURE