


Make:	Toyota	Model:	Avensis
Body Style:	Wagon	Year:	2003
Rego No.:	BQE609	Rego Expiry:	23 Nov 2026
WoF Expiry:	21 Sep 2026	Odometer:	242,407 Kms
Good No.:	27955145	VIN:	SB1ER56L30E037836
Next Service:	253,000 Kms	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Stone chips in front windscreen  
 Front bumper lower left side trim missing

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**

2WD  
 Engine oil seep

**Interior Comments**

Seats:	Stains. Slight wear on drivers seat
Carpets:	Good
Panels:	Good
Dashboard:	Good

**General Comments**

Partial service history  
 Rear interior light cover detached  
 One key remote is missing buttons  
 Gearbox noisy. Has been inspected by Toyota and advised that something is damaged

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Timing Chain	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No	Kms
Inspected by:	Hoani Saunders	
Published by:	Miroslav Granich	
Inspection Date:	02 Feb 2026	

I have read and understood  
 this condition guide:

NAME \_\_\_\_\_

Report ID:	27,955,145	Version:	1
Created:	02 Feb 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise		✓	
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	2.4 mm		
Right front	2.9 mm		
Left rear	4.4 mm		
Right rear	4.8 mm		
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	4		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE \_\_\_\_\_