


Make:	Hyundai	Model:	Elantra
Body Style:	Sedan	Year:	2006
Rego No.:	DFH733	Rego Expiry:	28 Mar 2026
WoF Expiry:	14 Mar 2026	Odometer:	234,632 Kms
Good No.:	27957088	VIN:	KMHDM41CR6U224376
Next Service:	230,500 Kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

2WD

Engine oil weep and seepage

Interior Comments

Seats:	Average
--------	---------

Carpets:	Average
----------	---------

Panels:	Average
---------	---------

Dashboard:	Average
------------	---------

General Comments

Clutch pedal play average

CD player isn't reading CD's

Silver key doesn't start vehicle

Graunch when shifting in to fourth gear from third gear

Road Conditions During Test Drive	Dry
-----------------------------------	-----

Engine Timing Mechanism	Cambelt
-------------------------	---------

Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	103,676 Kms
----------------------------------	---	-----------------------------	-------------

Inspected by:	Hoani Saunders
---------------	----------------

Published by:	Robert Chardon
---------------	----------------

Inspection Date:	03 Feb 2026
------------------	-------------

I have read and understood
this condition guide:

NAME _____

Report ID:	27,957,088	Version:	1
Created:	03 Feb 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	2.9 mm		
Right front	3.2 mm		
Left rear	5.1 mm		
Right rear	5.4 mm		
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	3		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			
Reversing camera			✓

SIGNATURE _____