


Make:	Audi	Model:	A6
Body Style:	Sedan	Year:	2003
Rego No.:	GSH468	Rego Expiry:	10 Mar 2026
WoF Expiry:	18 Dec 2026	Odometer:	218,568 Kms
Good No.:	27961772	VIN:	WAUZZZ4B43N062650
Next Service:	224780	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Excessive oil leaks
Headlights discoloured
Bumper trim missing

Interior Comments

Seats:	Poor
Carpets:	Poor
Panels:	Poor
Dashboard:	Poor

General Comments

- Engine light displayed
- Key fob not working
- Interior hood lining hanging down
- Left rear window slow to operate

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Cambelt		
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/> No
Inspected by:	Phillip Russel-Waimotu		
Published by:	Phillip Russel-Waimotu		
Inspection Date:	04 Feb 2026		

I have read and understood
this condition guide:

NAME

SIGNATURE