


Make:	Nissan	Model:	Fuga
Body Style:	Sedan	Year:	2011
Rego No.:	QPU625	Rego Expiry:	09 Apr 2026
WoF Expiry:	27 Nov 2026	Odometer:	168,574 Kms
Good No.:	27963076	VIN:	7AT0DH8GX24401129
Next Service:	172,000	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Conditions During Body Inspection	Dry
-----------------------------------	-----

Suspected Front left CV boot leak

Seats:	worn driver seat
Carpets:	Good
Panels:	Good
Dashboard:	Good

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Kilipati Mae		
Published by:	Kilipati Mae		
Inspection Date:	05 Feb 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____