


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Nissan | Model: | March |
| Body Style: | Hatchback | Year: | 2004 |
| Rego No.: | GPM71 | Rego Expiry: | 05 Feb 2026 |
| WoF Expiry: | 25 Feb 2026 | Odometer: | 197,576 Kms |
| Good No.: | 27964713 | VIN: | 7AT0DH0KX12271464 |
| Next Service: | 201,940 | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left wing mirror paint defect

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Underbody surface rust

Radiator support panel rust

Interior Comments

Seats: Driver seat worn

Carpets: Good

Panels: Good

Dashboard: Average

General Comments

Reverse lights not operating

| | |
|-----------------------------------|----------------------------------------------------------|
| Road Conditions During Test Drive | Dry |
| Engine Timing Mechanism | Unknown |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| | Kms |
| Inspected by: | Kilipati Mae |
| Published by: | Kilipati Mae |
| Inspection Date: | 05 Feb 2026 |

I have read and understood
this condition guide:

NAME _____

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,964,713 | Version: | 1 |
| Created: | 05 Feb 2026 | | |

| | OK | Requires Attention | N/A |
|-----------------------------------------------------|-----|--------------------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | 2 mm | |
| Right front | | 2 mm | |
| Left rear | | 3 mm | |
| Right rear | | 3 mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | | ✓ | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | | | ✓ |
| Window winder RR | | | ✓ |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 2 | | |
| Central locking | | ✓ | |
| Remote locking | | ✓ | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

SIGNATURE _____