


| | | | |
|---------------|--------------------|------------------|-------------------|
| Make: | Nissan | Model: | March |
| Body Style: | Hatchback | Year: | 2002 |
| Rego No.: | DYF72 | Rego Expiry: | 20 May 2026 |
| WoF Expiry: | 27 Oct 2026 | Odometer: | 90,307 Kms |
| Good No.: | 27965643 | VIN: | 7A8DH0K0707024677 |
| Next Service: | 15/3/22 or 90000km | Service History: | No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Boot hood struts worn, doesn't stay up.
 Surface corrosion RH side boot jam.
 Bonnet doesn't shut properly left hand side, bigger body gap also.

| | |
|-----------------------------------|-----|
| Conditions During Body Inspection | Dry |
|-----------------------------------|-----|

Under Carriage and Under Bonnet Inspection Comments
Interior Comments

| | |
|------------|---------|
| Seats: | Good |
| Carpets: | Average |
| Panels: | Average |
| Dashboard: | Good |

General Comments

Vehicle drove well.
 Air conditioning not cold.
 Service due.
 Drivers window goes down but plays up going up.

| | | |
|-----------------------------------|----------------------------------------------------------|-----|
| Road Conditions During Test Drive | Dry | |
| Engine Timing Mechanism | Timing Chain | |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> Yes <input type="checkbox"/> No | Kms |
| Inspected by: | Aaron Johnson | |
| Published by: | Aaron Johnson | |
| Inspection Date: | 12 Feb 2026 | |

I have read and understood
 this condition guide:

NAME _____

| | | | |
|------------|-------------|----------|---|
| Report ID: | 27,965,643 | Version: | 1 |
| Created: | 12 Feb 2026 | | |

| | OK | Requires Attention | N/A |
|-----------------------------------------------------|----|--------------------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | 6 mm | |
| Right front | | 6 mm | |
| Left rear | | 6 mm | |
| Right rear | | 6 mm | |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | | | ✓ |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | | | ✓ |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

SIGNATURE _____