

Report ID:	27,967,255	Version:	1
Created:	11 Feb 2026		


Make:	Subaru	Model:	Impreza
Body Style:	Sedan	Year:	2009
Rego No.:	LHT27	Rego Expiry:	01 Aug 2026
WoF Expiry:	11 Oct 2026	Odometer:	199,981 Kms
Good No.:	27967255	VIN:	7AT0GF09X17634346
Next Service:	210,000 Kms	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Stone chips in front windscreen
Front bumper tow hook cover missing
Front right park and spot lights aren't working
Rear bumper side skirts held on with tape at rear end

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

AWD

Interior Comments

Seats:	Large rip on drivers seat
Carpets:	Average
Panels:	Centre console lid loose
Dashboard:	Good

General Comments

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No 125,565 Kms
Inspected by:	Hoani Saunders
Published by:	Malcolm Thomas
Inspection Date:	11 Feb 2026

I have read and understood
this condition guide:

NAME _____

SIGNATURE _____

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5.5 mm
Right front			5.6 mm
Left rear			2.8 mm
Right rear			3.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights		✓	
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera		✓	