

Report ID:	27,967,841	Version:	1
Created:	08 Feb 2026		


Make:	Hyundai	Model:	I30
Body Style:	Hatchback	Year:	2011
Rego No.:	FYP832	Rego Expiry:	25 Mar 2026
WoF Expiry:	26 Jul 2026	Odometer:	241,255 Kms
Good No.:	27967841	VIN:	KMHDB51DMBU344637
Next Service:	245000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

- Front bumper misaligned
- Left indicator light cover missing
- Spider rust on roof
- Minor chips on windscreen

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Underbody surface rust

Interior Comments

Seats:	stained
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

FL low beam light not working
EP window doesn't work with master switch

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Phillip Russel-Waimotu		
Published by:	Phillip Russel-Waimotu		
Inspection Date:	08 Feb 2026		

I have read and understood
this condition guide:

NAME _____

SIGNATURE

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			3 mm
Right front			3 mm
Left rear			5 mm
Right rear			4 mm
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR		✓	
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓