


Make:	Ford	Model:	Territory
Body Style:	SUV	Year:	2013
Rego No.:	GUQ260	Rego Expiry:	28 Mar 2026
WoF Expiry:	12 Dec 2026	Odometer:	186,678 Kms
Good No.:	27968438	VIN:	6FPAAJGATDM27533
Next Service:	194,000 Kms	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**

AWD

Rear bump stops wearing out

**Interior Comments**

Seats:	Slight wear on driver seat
Carpets:	Wear on drivers side
Panels:	Good
Dashboard:	Glovebox lid faulty

**General Comments**

Partial service history

Interior roof lining pulling away at front end

Glovebox release lever clip broken internally

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
	181,700 Kms
Inspected by:	Hoani Saunders
Published by:	Robert Chardon
Inspection Date:	09 Feb 2026

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	27,968,438	Version:	1
Created:	10 Feb 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front	5.3 mm		
Right front	4.9 mm		
Left rear	5.3 mm		
Right rear	5.4 mm		
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

SIGNATURE \_\_\_\_\_