


Make:	Toyota	Model:	Altezza
Body Style:	Sedan	Year:	1999
Rego No.:	ETB110	Rego Expiry:	28 Mar 2026
WoF Expiry:	05 Jul 2026	Odometer:	160,683 Kms
Good No.:	27968982	VIN:	7A8H6390708030577
Next Service:		Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Damage to left front guard
Extremely rusted underbody

Conditions During Body Inspection

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Poor

General Comments

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Cambelt		
Evidence of Cam Belt Replacement	<input type="checkbox"/>	Yes	<input checked="" type="checkbox"/> No
Inspected by:	Phillip Russel-Waimotu		
Published by:	Phillip Russel-Waimotu		
Inspection Date:	10 Feb 2026		

I have read and understood
this condition guide:

NAME

SIGNATURE