


Make:	Mazda	Model:	Verisa
Body Style:	Hatchback	Year:	2007
Rego No.:	LAE539	Rego Expiry:	13 May 2026
WoF Expiry:	03 Sep 2026	Odometer:	145,000 Kms
Good No.:	27971204	VIN:	7AT0C103X17309040
Next Service:	N/A	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front of bonnet trim is cracked
 Rear bumper fitment severely off
 Boot trim cracked with severe denting
 Around boot latch has botched rust repair job

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Underbody surface rust

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

FWD
 Two keys, one is valet and one is remote (not working)

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Ryan Scott
Published by:	Robert Chardon
Inspection Date:	10 Feb 2026

I have read and understood
 this condition guide:

NAME _____

Report ID:	27,971,204	Version:	1
Created:	11 Feb 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front		4.8 mm	
Right front		4.7 mm	
Left rear		3.0 mm	
Right rear		3.3 mm	
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)			✓
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE _____