


Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2013
Rego No.:	JYY150	Rego Expiry:	02 Mar 2026
WoF Expiry:	09 Jul 2026	Odometer:	137,500 Kms
Good No.:	27972500	VIN:	MNAUMFF50DW203511
Next Service:	151000 kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Front interior dome light trim cracked. Headliner stains. Front seat plastics cracked. Front door check strap clicks. Tray hard lid right latch not latching. Front bumper grille loose. Headlights fading. Front tyres scalloped.

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**

Engine oil leaks and stains. Underbody surface rust (minor). Front upper control arm ball joint boots cracked. Exhaust flange leak.

**Interior Comments**

Seats:	Average
Carpets:	Average
Panels:	Average, interior trims loose/damage.
Dashboard:	Average, has holes and right vent cracked.

**General Comments**

ODO: 137230 kms. Gear knob wear.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No
Inspected by:	Eleoit Kumar
Published by:	Eleoit Kumar
Inspection Date:	09 Feb 2026

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

Report ID:	27,972,500	Version:	1
Created:	09 Feb 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front		6 mm	
Right front		6 mm	
Left rear		9 mm	
Right rear		9 mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights			✓
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

SIGNATURE \_\_\_\_\_