

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Under Carriage and Under Bonnet Inspection Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Gary Adams		
Published by:	Luke Saunders		
Inspection Date:	12 Feb 2026		

NAME _____

SIGNATURE

Reversing camera			✓
------------------	--	--	---