


Report ID:	27,984,561	Version:	1
Created:	14 Feb 2026		

Make:	Volkswagen	Model:	Golf
Body Style:	Hatchback	Year:	2006
Rego No.:	RPN996	Rego Expiry:	24 Nov 2026
WoF Expiry:	20 Apr 2026	Odometer:	185,516 Kms
Good No.:	27984561	VIN:	WVWZZZ1KZ5U024858
Next Service:	186,380	Service History:	No

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left wing mirror scratched. Right wing mirror indicator lens cracked.

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Rip in drivers seat.
Carpets:	Average
Panels:	Average
Dashboard:	Good

General Comments

AC not blowing cold. Bulb light on dashboard. Dashboard display in poor condition. Heater Fan controls not working. Bonnet struts need re-gassing. Rear wiper not working. Left brake light not working. Exhaust leak. Coolant leak. Oil leaks.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Cambelt		
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	160,402 Kms
Inspected by:	Lewis Dolamore		
Published by:	Lewis Dolamore		
Inspection Date:	14 Feb 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance		✓	
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5 mm
Right front			5 mm
Left rear			3 mm
Right rear			4 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)		✓	
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____