

Report ID:	28,001,122	Version:	1
Created:	25 Feb 2026		


Make:	Nissan	Model:	Dualis
Body Style:	Wagon	Year:	2009
Rego No.:	LNL142	Rego Expiry:	30 Jun 2026
WoF Expiry:	19 Nov 2026	Odometer:	184,592 Kms
Good No.:	28001122	VIN:	7AT0DH7HX18206834
Next Service:		Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			7.0 mm
Right front			7.0 mm
Left rear			7.0 mm
Right rear			7.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)		✓	
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

Body Inspection Comments

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Vendor advised the vehicle was recently scanned and fault codes P2138 & P1726 were present - check engine light not currently on (may be on by the time the vehicle is collected). Oil leak.

Interior Comments

Seats:	drivers split
Carpets:	Average
Panels:	marks scratch scuffs
Dashboard:	Average

General Comments

Rear wiper smears

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Gary Adams
Published by:	Luke Saunders
Inspection Date:	24 Feb 2026

I have read and understood this condition guide:

NAME _____

SIGNATURE _____