

Report ID:	28,004,949	Version:	1
Created:	26 Feb 2026		


Make:	BMW	Model:	3 Series
Body Style:	Sedan	Year:	2007
Rego No.:	QYH252	Rego Expiry:	19 Apr 2026
WoF Expiry:	08 Sep 2026	Odometer:	202,962 Kms
Good No.:	28004949	VIN:	WBAVC36000NE64107
Next Service:	206,000 Kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

- Paint defect on side mirrors and cant rails.
- Bootlid struts need regassed/replaced.
- Stonechips/crack in windscreen.
- LH skirt scuffed.

Conditions During Body Inspection	Dry
-----------------------------------	-----

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Good. Minor tear on drivers seat bolster.
Carpets:	Good
Panels:	Good
Dashboard:	Average, steering wheel worn.

General Comments

- Front window washers not spraying.
- LR seat child seat anchor point covers missing.
- Bulb warning light on dash, RH reverse light not working.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms
Inspected by:	Troy Smith
Published by:	Troy Smith
Inspection Date:	26 Feb 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			6.5 mm
Right front			6 mm
Left rear			3 mm
Right rear			6.5 mm
Spare		No	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)		✓	
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____