

Report ID:	28,011,834	Version:	1
Created:	26 Feb 2026		


Make:	Toyota	Model:	Landcruiser Prado
Body Style:	Wagon	Year:	1991
Rego No.:	BPL328	Rego Expiry:	18 Jun 2025
WoF Expiry:	24 Aug 2026	Odometer:	296,011 Kms
Good No.:	28011834	VIN:	7A8H60H0799017007
Next Service:	Unreadable	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Both A pillar pin dent & rust
 Bonnet is catching to firewall cover panel

Conditions During Body Inspection Wet

Under Carriage and Under Bonnet Inspection Comments

Subframe rust
 Underbody surface rust
 Oil leak (requires further investigation)
 Leak in transfer case

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	door cards torn
Dashboard:	Average

General Comments

Front left window regulator panel loose
 No cover panel on the master window regulator controls
 Noise in steering column
 Noise in suspension

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Unknown
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms

Inspected by:	Kilipati Mae
Published by:	Kilipati Mae
Inspection Date:	26 Feb 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			10 mm
Right front			12 mm
Left rear			11 mm
Right rear			10 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)			✓
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____