


Make:	Toyota	Model:	Corolla
Body Style:	Hatchback	Year:	2008
Rego No.:	RMR707	Rego Expiry:	22 Jul 2026
WoF Expiry:	08 Jul 2026	Odometer:	238,363 Kms
Good No.:	28016392	VIN:	JTNKU58E101063592
Next Service:	243000	Service History:	No

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Stonechips on windscreen

Front wheel drive

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	☐ Yes	☐ No	Kms
Inspected by:	Cameron Senior-Arnold		
Published by:	Jaykib Collins		
Inspection Date:	01 Mar 2026		

NAME _____

SIGNATURE