


|               |             |                  |                   |
|---------------|-------------|------------------|-------------------|
| Make:         | Nissan      | Model:           | Navara            |
| Body Style:   | Utility     | Year:            | 2018              |
| Rego No.:     | LTN993      | Rego Expiry:     | 21 Feb 2027       |
| WoF Expiry:   | 06 Nov 2026 | Odometer:        | 148,291 Kms       |
| Good No.:     | 28021049    | VIN:             | MNTCB2D23A0012610 |
| Next Service: | 160,300     | Service History: | No                |

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

## Black spores or roof

### Under Carriage and Under Bonnet Inspection Comments

|            |                  |
|------------|------------------|
| Seats:     | driver seat worn |
| Carpets:   | Good             |
| Panels:    | Good             |
| Dashboard: | Good             |

One key for tray lid  
Headunit needs to be updated (unable to check nav.reverse camera ETC)

I have read and understood  
this condition guide:

NAME \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

|                                              | OK   | Requires<br>Attention | N/A |
|----------------------------------------------|------|-----------------------|-----|
| Engine                                       |      |                       |     |
| Oil level                                    | ✓    |                       |     |
| Smoke & fumes                                | ✓    |                       |     |
| Engine performance                           | ✓    |                       |     |
| Noise                                        | ✓    |                       |     |
| Coolant condition                            | ✓    |                       |     |
| Cooling performance                          | ✓    |                       |     |
| Radiator / Hoses (visual)                    | ✓    |                       |     |
| Transmission                                 |      |                       |     |
| Operation                                    | ✓    |                       |     |
| Noise                                        | ✓    |                       |     |
| Clutch                                       |      |                       | ✓   |
| CV joints                                    | ✓    |                       |     |
| Wheel bearings                               | ✓    |                       |     |
| Brakes                                       |      |                       |     |
| Performance                                  | ✓    |                       |     |
| Hand brake                                   | ✓    |                       |     |
| Tyres (lowest observed tread depth of tyres) |      |                       |     |
| Left front                                   | 6 mm |                       |     |
| Right front                                  | 8 mm |                       |     |
| Left rear                                    | 2 mm |                       |     |
| Right rear                                   | 3 mm |                       |     |
| Spare                                        | Yes  |                       |     |
| Suspension                                   |      |                       |     |
| Suspension performance                       | ✓    |                       |     |
| Steering performance                         | ✓    |                       |     |
| Shock absorbers                              | ✓    |                       |     |
| Air Conditioning / Heater                    |      |                       |     |
| Operation                                    | ✓    |                       |     |
| Electrical / Accessories                     |      |                       |     |
| Head lights                                  | ✓    |                       |     |
| Tail lights                                  | ✓    |                       |     |
| Indicators                                   | ✓    |                       |     |
| Dashboard warning lights                     | ✓    |                       |     |
| Wipers (front & rear)                        | ✓    |                       |     |
| Window winder FL                             | ✓    |                       |     |
| Window winder FR                             | ✓    |                       |     |
| Window winder RL                             | ✓    |                       |     |
| Window winder RR                             | ✓    |                       |     |
| Rear view mirrors                            | ✓    |                       |     |
| Radio (basic test only)                      |      |                       | ✓   |
| CD (basic test only)                         |      |                       | ✓   |
| Number of keys                               | 1    |                       |     |
| Central locking                              | ✓    |                       |     |
| Remote locking                               | ✓    |                       |     |
| Sat. nav. (basic test only)                  |      |                       | ✓   |
| Reversing camera                             |      |                       | ✓   |