


Report ID:	28,038,421	Version:	4
Created:	27 Mar 2026		

Make:	Mazda	Model:	Axela
Body Style:	Hatchback	Year:	2010
Rego No.:	JJE743	Rego Expiry:	13 Mar 2026
WoF Expiry:		Odometer:	138,461 Kms
Good No.:	28038421	VIN:	7AT0C13JX15109651
Next Service:	123500o	Service History:	No

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Stonechip in CVA/Top boot frame structure surface rust

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

2wd/minor underbody surface rust/

Interior Comments

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Vibration on idle/front suspension knocks/No Active WOF on vehicle
 Front left wheel buckled/damaged Left & Right tyre sidewall split front
 Back right wheel buckled / Left & Right tyre sidewall split front
 Left & Right tyre sidewall split front / Right rear plate number light lamp not working

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms

Inspected by:	Uriah Pepene
Published by:	David McDonnell
Inspection Date:	12 Mar 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise		✓	
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5.5 mm
Right front			5.5 mm
Left rear			5.5 mm
Right rear			5.5 mm
Spare		Yes	
Suspension			
Suspension performance		✓	
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____