

Report ID:	28,043,016	Version:	1
Created:	20 Mar 2026		


Make:	Mitsubishi	Model:	Triton
Body Style:	Utility	Year:	2018
Rego No.:	LLC332	Rego Expiry:	27 Jun 2026
WoF Expiry:	01 Apr 2027	Odometer:	231,147 Kms
Good No.:	28043016	VIN:	MMAJYKK10HH025765
Next Service:	241148	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

- Left tail light is cracked
- Minor stone chips on windscreen
- Roof rack keys missing
- Noted rust on body is surface rust

Conditions During Body Inspection    Dry

**Under Carriage and Under Bonnet Inspection Comments**

Rear wheel drive

**Interior Comments**

Seats:	Drivers seat torn, Good
Carpets:	Drivers floor torn, Good
Panels:	Good
Dashboard:	Good

**General Comments**

Partial service history (gaps between services last recorded at 186570kms)

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No    Kms
Inspected by:	Jaykib Collins
Published by:	Janine Bell
Inspection Date:	14 Mar 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			4.0 mm
Right front			5.5 mm
Left rear			3.0 mm
Right rear			6.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_