

Report ID:	28,044,567	Version:	1
Created:	16 Mar 2026		


Make:	Subaru	Model:	Legacy
Body Style:	Wagon	Year:	2006
Rego No.:	MAD975	Rego Expiry:	26 Mar 2026
WoF Expiry:	13 Mar 2027	Odometer:	186,073 Kms
Good No.:	28044567	VIN:	7AT0GF0BX18027946
Next Service:	195,698kms	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Right door mirror repeater has minor crack. Rear body kit had been removed(in the vehicle). Left side of rear bumper is not fitted correctly. Out side edge wear on left front tyre. Front grille is not fitted correctly.

Conditions During Body Inspection	Dry
-----------------------------------	-----

**Under Carriage and Under Bonnet Inspection Comments**

Weeping from engine. Rear sway bar has play and rattling.

**Interior Comments**

Seats:	Right front base pad is torn.
Carpets:	Right front is worn.
Panels:	Good
Dashboard:	Surface is cracked.

**General Comments**

After market exhaust (no silencer) sounds loud. Left rear door lock actuator is not operating. Right front speaker is faulty. Horn is faulty.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No    Kms
Inspected by:	Yuki Itohara
Published by:	Glen Charlton
Inspection Date:	12 Mar 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			2.0 mm
Right front			4.5 mm
Left rear			6.0 mm
Right rear			6.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking		✓	
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_