


Report ID:	28,053,571	Version:	1
Created:	25 Mar 2026		

Make:	Toyota	Model:	Corolla
Body Style:	Hatchback	Year:	2004
Rego No.:	HCP319	Rego Expiry:	10 Aug 2026
WoF Expiry:	21 Jan 2027	Odometer:	237,920 Kms
Good No.:	28053571	VIN:	7AT0H607X13315806
Next Service:	245,000	Service History:	Yes

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Headlights faded.  
 Front bumper in poor condition and poor fit, piece missing.  
 Rear bumper poor fit.

Conditions During Body Inspection    Dry

### Under Carriage and Under Bonnet Inspection Comments

Evidence of oil leak from top and bottom of motor.  
 Front brake rotors have rust pitting.

### Interior Comments

Seats:	Average
Carpets:	ware patch drivers footwell.
Panels:	Average
Dashboard:	Average

### General Comments

1 out of 2 physical keys doesn't match drivers door.  
 Remote locking not working

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Finlay Lemmens		
Published by:	Laura Iovine		
Inspection Date:	17 Mar 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance		✓	
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			6.0 mm
Right front			5.0 mm
Left rear			4.0 mm
Right rear			4.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking		✓	
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_