

Report ID:	28,063,356	Version:	3
Created:	30 Mar 2026		


Make:	Toyota	Model:	Hiace
Body Style:	Van	Year:	2016
Rego No.:	JZP154	Rego Expiry:	15 Aug 2026
WoF Expiry:	18 Feb 2027	Odometer:	143,200 Kms
Good No.:	28063356	VIN:	JTFHT02P705023015
Next Service:	156,000 kms	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

### Key

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Note: cargo van has hole and rust, number plate light not working, spare wheel rust, paint worn driver's door opening painted surface, cargo interior cargo trim boards damage, tow bar/ball rusty, roof rust.

Conditions During Body Inspection: Wet

### Under Carriage and Under Bonnet Inspection Comments

Left front tyre edge worn.

### Interior Comments

Seats:	Poor
Carpets:	Poor
Panels:	Average
Dashboard:	Average

### General Comments

Driver seat belt frayed weak to retract, driver seat torn, windscreen cracked out cva, dashboard have hole.

Road Conditions During Test Drive	Wet
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    141,000 Kms
Inspected by:	Marlon Espena
Published by:	Henry Manders
Inspection Date:	26 Mar 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			8.0 mm
Right front			8.0 mm
Left rear			7.0 mm
Right rear			7.0 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_