

Report ID:	28,066,559	Version:	1
Created:	24 Mar 2026		


Make:	Toyota	Model:	Hilux
Body Style:	Utility	Year:	2006
Rego No.:	DDE716	Rego Expiry:	25 Jan 2027
WoF Expiry:	20 Jan 2027	Odometer:	252,970 Kms
Good No.:	28066559	VIN:	MR0CZ12G600007183
Next Service:	no sticker	Service History:	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

- Front bumper misalignment
- Left tail light cracked
- Left sill gauge
- Right b - pillar paint run, left B pillar stone chip and rust

Conditions During Body Inspection: Dry

**Under Carriage and Under Bonnet Inspection Comments**

- Rusty flat deck sides
- Underbody surface rust
- Subframe rusty

**Interior Comments**

Seats:	driver seat torn
Carpets:	Average
Panels:	Average
Dashboard:	Average

**General Comments**

- Partial service history
- Left daytime running light not working

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    Kms
Inspected by:	Sione Mae
Published by:	Sione Mae
Inspection Date:	24 Mar 2026

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			2 mm
Right front			4 mm
Left rear			6 mm
Right rear			6 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights		✓	
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking			✓
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_