


Report ID:	28,066,585	Version:	1
Created:	20 Mar 2026		

Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2013
Rego No.:	HDL913	Rego Expiry:	24 Nov 2026
WoF Expiry:	16 Jan 2027	Odometer:	223,198 Kms
Good No.:	28066585	VIN:	MNAUMFF50DW220081
Next Service:	230723 kms	Service History:	No

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**  
 S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

### Body Inspection Comments

Headliner marks. Steering control buttons missing. Steering wheel and gear knob worn. LF door seal damage. Front seat plastic bases loose/broken. Rear bumper pushed in.

Conditions During Body Inspection: Dry

### Under Carriage and Under Bonnet Inspection Comments

Brake master cylinder cap incorrect. Upper control arm ball joint boots cracking. Front crash bar bends and dents.

### Interior Comments

Seats:	Average
Carpets:	Average, driver floor tear
Panels:	Average
Dashboard:	Average

### General Comments

\*Side view mirror controls pushed in. Clutch engagement near top of pedal travel. W/S rear view mirror loose.

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Eleoit Kumar		
Published by:	Eleoit Kumar		
Inspection Date:	20 Mar 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch		✓	
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			8 mm
Right front			8 mm
Left rear			9 mm
Right rear			9 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors		✓	
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_