

Report ID:	28,068,349	Version:	1
Created:	24 Mar 2026		


Make:	Holden	Model:	Epica
Body Style:	Sedan	Year:	2007
Rego No.:	ERT360	Rego Expiry:	02 Sep 2026
WoF Expiry:	14 Jun 2026	Odometer:	217,233 Kms
Good No.:	28068349	VIN:	KL3LA69LJ8B114027
Next Service:	140000	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

- Front bumper misaligned
- Rear bumper misaligned
- Right taillight cracked
- Right side skirt missing

Conditions During Body Inspection    Dry

**Under Carriage and Under Bonnet Inspection Comments**

Suspected noisy wheel bearing, requires further investigation

**Interior Comments**

Seats:	Average
Carpets:	Average
Panels:	Average
Dashboard:	Average

**General Comments**

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Sione Mae		
Published by:	Sione Mae		
Inspection Date:	24 Mar 2026		

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes		✓	
Engine performance	✓		
Noise		✓	
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings		✓	
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			3 mm
Right front			4 mm
Left rear			5 mm
Right rear			5 mm
Spare			
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_