


Report ID:	28,084,382	Version:	3
Created:	26 May 2026		

Make:	Holden	Model:	Colorado
Body Style:	Utility	Year:	2019
Rego No.:	MDY166	Rego Expiry:	27 Aug 2026
WoF Expiry:	12 May 2027	Odometer:	225,348 Kms
Good No.:	28084382	VIN:	MMU148EK0KH661944
Next Service:	235,326	Service History:	No

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection: Dry Wet

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

Seats:	Stains
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Cambelt		
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	162,803 Kms
Inspected by:	Samuel Weir		
Published by:	Desian Robb		
Inspection Date:	30 Mar 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	<input checked="" type="checkbox"/>		
Smoke & fumes	<input checked="" type="checkbox"/>		
Engine performance	<input checked="" type="checkbox"/>		
Noise	<input checked="" type="checkbox"/>		
Coolant condition	<input checked="" type="checkbox"/>		
Cooling performance	<input checked="" type="checkbox"/>		
Radiator / Hoses (visual)	<input checked="" type="checkbox"/>		
Transmission			
Operation	<input checked="" type="checkbox"/>		
Noise	<input checked="" type="checkbox"/>		
Clutch			<input checked="" type="checkbox"/>
CV joints			<input checked="" type="checkbox"/>
Wheel bearings	<input checked="" type="checkbox"/>		
Brakes			
Performance	<input checked="" type="checkbox"/>		
Hand brake	<input checked="" type="checkbox"/>		
Tyres (lowest observed tread depth of tyres)			
Left front			8.0 mm
Right front			8.0 mm
Left rear			8.0 mm
Right rear			8.0 mm
Spare		<input checked="" type="checkbox"/> Yes	
Suspension			
Suspension performance	<input checked="" type="checkbox"/>		
Steering performance	<input checked="" type="checkbox"/>		
Shock absorbers	<input checked="" type="checkbox"/>		
Air Conditioning / Heater			
Operation	<input checked="" type="checkbox"/>		
Electrical / Accessories			
Head lights	<input checked="" type="checkbox"/>		
Tail lights	<input checked="" type="checkbox"/>		
Indicators	<input checked="" type="checkbox"/>		
Dashboard warning lights	<input checked="" type="checkbox"/>		
Wipers (front & rear)	<input checked="" type="checkbox"/>		
Window winder FL	<input checked="" type="checkbox"/>		
Window winder FR	<input checked="" type="checkbox"/>		
Window winder RL	<input checked="" type="checkbox"/>		
Window winder RR	<input checked="" type="checkbox"/>		
Rear view mirrors	<input checked="" type="checkbox"/>		
Radio (basic test only)	<input checked="" type="checkbox"/>		
CD (basic test only)			<input checked="" type="checkbox"/>
Number of keys	2		
Central locking	<input checked="" type="checkbox"/>		
Remote locking	<input checked="" type="checkbox"/>		
Sat. nav. (basic test only)			<input checked="" type="checkbox"/>
Reversing camera	<input checked="" type="checkbox"/>		

I have read and understood this condition guide:

NAME _____

SIGNATURE _____