

Report ID:	28,085,017	Version:	1
Created:	01 Apr 2026		


Make:	Mazda	Model:	Verisa
Body Style:	Hatchback	Year:	2004
Rego No.:	JRT300	Rego Expiry:	21 Feb 2026
WoF Expiry:	24 Apr 2026	Odometer:	162,233 Kms
Good No.:	28085017	VIN:	7AT0C103X16108140
Next Service:	155,131km's	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Large dent in left side of bonnet. Paint worn on roof, top of tailgate & both left side door panels.

Conditions During Body Inspection

Dry

Under Carriage and Under Bonnet Inspection Comments

Oil leak from engine. Underbody surface rust.

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good

General Comments

Engine oil service is well overdue. Play in drivers seat rails. Cd player is not working. A/C is not getting cold, needs attention. Left front headlight is not working on low beam. (Need to use blade key to start).

Road Conditions During Test Drive	Dry		
Engine Timing Mechanism	Timing Chain		
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	Kms
Inspected by:	Jason Young		
Published by:	Glen Charlton		
Inspection Date:	01 Apr 2026		

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			4.0 mm
Right front			4.5 mm
Left rear			4.4 mm
Right rear			5.2 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights		✓	
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____