

Report ID:	28,087,218	Version:	1
Created:	31 Mar 2026		


Make:	Mitsubishi	Model:	L300
Body Style:	Van	Year:	2009
Rego No.:	FES846	Rego Expiry:	22 Jul 2026
WoF Expiry:	25 Feb 2027	Odometer:	217,384 Kms
Good No.:	28087218	VIN:	JMASNP04VAA800262
Next Service:	222000	Service History:	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key**

S = Scratch    R = Rust    C = Crack    \* = Decals    W = Significant scuffs  
 D = Dent    PT = Paint defect    P = Pin dent    SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

**Body Inspection Comments**

Engine check light on/draws fitted in rear/

Conditions During Body Inspection

Dry

**Under Carriage and Under Bonnet Inspection Comments**

2wd/underbody surface rust/engine oil leak/

**Interior Comments**

Seats: drivers bottom pad ripped

Carpets: Average

Panels: Average

Dashboard: Average

**General Comments**

Clutch engagement point top of pedal/steering pull left

Road Conditions During Test Drive	Dry	
Engine Timing Mechanism	Cambelt	
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Inspected by:	Uriah Pepene	
Published by:	Uriah Pepene	
Inspection Date:	31 Mar 2026	

	OK	Requires Attention	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch		✓	
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand brake	✓		
<b>Tyres (lowest observed tread depth of tyres)</b>			
Left front			6 mm
Right front			6 mm
Left rear			4 mm
Right rear			4 mm
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance		✓	
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation			✓
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME \_\_\_\_\_

SIGNATURE \_\_\_\_\_