

Report ID:	28,087,963	Version:	2
Created:	04 May 2026		


Make:	Mazda	Model:	Atenza
Body Style:	Sedan	Year:	2014
Rego No.:	QJT213	Rego Expiry:	15 Sep 2025
WoF Expiry:	28 Aug 2026	Odometer:	176,141 Kms
Good No.:	28087963	VIN:	7AT0C139X23101953
Next Service:		Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left headlight is damaged, stone chips & scratches in the windscreen, pin dents in both cant rails, left side skirt cracked, both rear tow eye covers missing, right rear reflector damaged, rear bumper needs alignment,

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Oil level over full, coolant level low,

Interior Comments

Seats:	stains, wear and tear,
Carpets:	Average
Panels:	stains
Dashboard:	Average

General Comments

Radio does not work due to missing sd card, left rear indicator not working, i stop light flashing, airbag warning light on,

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Timing Chain
Evidence of Cam Belt Replacement	<input type="checkbox"/> Yes <input type="checkbox"/> No Kms

Inspected by:	Jesse Roberts
Published by:	Jesse Roberts
Inspection Date:	30 Mar 2026

	OK	Requires Attention	N/A
Engine			
Oil level		✓	
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition		✓	
Cooling performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			5.0 mm
Right front			4.4 mm
Left rear			5.8 mm
Right rear			5.4 mm
Spare		N/A	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators		✓	
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____