


Report ID:	28,101,107	Version:	1
Created:	09 Apr 2026		

Make:	Subaru	Model:	Legacy
Body Style:	Wagon	Year:	2003
Rego No.:	FYD221	Rego Expiry:	03 Jul 2026
WoF Expiry:	10 Mar 2027	Odometer:	246,460 Kms
Good No.:	28101107	VIN:	7AT0GF0BX11026553
Next Service:	249,000kms	Service History:	No

Note: This report is not a warranty
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key
 S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
 D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Front bumper is not fitted correctly. Minor stone cracks in windshield. Right bottom part of rear bumper is missing. Both side body kits are scuffed.

Conditions During Body Inspection: Dry

Under Carriage and Under Bonnet Inspection Comments

Left front drive shaft boot is torn. Leaking from engine. Coolant is leaking from lower hose joint. Rear tyres has inside edge wear.

Interior Comments

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Minor surface cracks.

General Comments

Transmission has minor shuddering. No power for audio unit and clock.

Road Conditions During Test Drive	Dry
Engine Timing Mechanism	Cambelt
Evidence of Cam Belt Replacement	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No 180,000 Kms
Inspected by:	Yuki Itohara
Published by:	Callum Busuttill
Inspection Date:	08 Apr 2026

	OK	Requires Attention	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Engine performance	✓		
Noise	✓		
Coolant condition	✓		
Cooling performance	✓		
Radiator / Hoses (visual)		✓	
Transmission			
Operation		✓	
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front			4.5 mm
Right front			5.0 mm
Left rear			3.0 mm
Right rear			3.0 mm
Spare		Yes	
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide:

NAME _____

SIGNATURE _____